





MODEL 4

This solution is adopted because of the interior layout of the housings in the building and the lack of connection between the existing stair and the outside of the building. By implementing this solution, we carry out the total reconstruction of the stair and the installation of a lift in the available outdoor area to provide service for the users of the floor.


ESTADO ACTUAL
PLANTA PORTAL




ESTADO ACTUAL
PLANTA TIPO



ESTADO REFORMADO
PLANTA PORTAL



ESTADO REFORMADO
PLANTA TIPO



IV

COTAS EN MILIMETROS



IV



IV



IV