







# MODEL 6

The usual technical solution for this type of installation, where the stairwell is wide, would consist of cutting the current stair steps and supporting the stair on the Modular Structure; but in this Model 6, when it's about old buildings where the stair has not appropriate safety or it is in a poor condition, we proceed to its total reconstruction and the installation of a lift in the available indoor area to provide service for the users of the floor.






VI



VI



VI



R